<b>Work Urder</b> April-11-14 9:21:0		51 Y	ef	*109	3951	•			Page 1
Revision ID:	3512-041 earplate Assemb			Accept	*N90	<b>1</b> 0040	1100*	Setup S	tart *NS1*
Start Date: 12, Required Date: 12, Reference:		tart Qty: 8.00 eq'd Qty: 8.00	*8* *8*		Cust l Custo	tem ID: mer:			
• •	rocess Plan: _ OC:	h	Date:	Tooling: SPC (Y/N):		Date: Date:		ſ	*NR1* *NR2*
Sequence ID/ Work Center ID		peration escription		Set Up/ Run Hours	Tool	ID Tool#	Plan Acc Code Qty		t Reject Insp. Number Stamp
Draw Nbr	Revisio	n Nbr			-		0		
D3512	D		`		i :/				
120 *1.20* Large Fab	La	arge Fab	DECOMA.	0.00	004				
Large Fab		A/R 2059b 2- Weld D3	rd surface using DT8874  Hardcoat Rod  512-3 spacer to D3512-:	as per Dwg D3512 & QSI  as per dwg	004		\\ \\	Lol	
130	Q	C9- Inspect visual per	QSI004- Fusion Welds	0.00	1			P.C	
*120* QC Quality Control		Memo		0.00	i				

•	of the commence of the final section of the section	1	
			1
			1 3
			1 4
			1 3
			-
			1
			1
		1	
		!	
			1
4.			Ś
			Ę
		i	1
			1
	·	1	
		1	
			3
			• •
6 V C 6 V C 6 V C			
# 25 \$1 \$2,			
a., }.			
<b>6</b> .			
		1	
ida e			
· *			
<b>8</b> '			
		: : :	
·			
60 C C			
# 			
•			
· .			
	And the state of t	l	
- Control Services and the services are the services and the services and the services are	THE PROPERTY OF CASE AND A THE PROPERTY OF THE	1 -	

Work Ord April-11-14 9:2		)9951		*109	951	*						Page 2
Item ID: Revision ID:	D3512-041			Accept	*N9	nn	<b>040</b>	100	<b>)*</b> s	etup Sta	rt *N;	S1*
Item Name:	Wearplate A	ssembly			1					Sto	<sup>p</sup> *N	S2*
Start Date: Required Date Reference:	12/09/13 : 12/23/13	Start Qty: 8.00 Req'd Qty: 8.00	*8* *8*			Item I comer:	D:			Q,		
Approvals:	Process P	lan:	Date:	Tooling:		D:	ate:		R	Run Sta	~1 <i>V</i> 1	R1*
••			Date:	SPC (Y/N):		Da	ate:			Sto	*N	R2*
Sequence ID/ Work Center I	D	Operation Description		Set Up/ Run Hours	То	ol ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
140		QC5- Inspect part comp	eteness to step on W/O	0.00	į							
*140* QC Quality Control		Мето		0.00		!					<del>.</del>	
						i						
150		Identify as per dwg & St	ock Location:	0.00		i !						
*150* Packaging		Memo		0.00		İ						

0.00

0.00

Packaging

160

\*160\*

Quality Control

QC21- Final Inspection - Work Order Release

Memo

## **Picklist Print**

April-11-14 9:21:05 AM

Work Order ID: 109951

\*109951\*

Parent Item:

D3512-041

\*D3512-041\*

Parent Item Name: Wearplate Assembly

**Start Date:** 12/09/13

Required Date: 12/23/13

Start Qty: 8.00

Required Qty: 8.00

**Comments:** 

IPP REV:A 13.07.19 NEW ISSUE DD VERF:JLM

IPP

	REV:B 13.12.11 1	ECN13-619/ REV	.D DW	G DD VERF	:JLM 								
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3512-3		Manufactured	No				Each	16.0000		8			
*D3512-3*	<b>k</b>						i i		**				
				Location		Loc	Qty 1	Loc Code					
				WA001			16		_		_		
					113028		16		_		_		
M304S18GA		Purchased	No			100	sf	409.9600		4			
*M304S18	RGA*						:   		**			<del> </del>	<del></del>
				Location		<u>Loc</u>	Oty	Loc Code					
				MAT019		39	97.96				_		
					117188		3				_		

<b>Location</b>	Loc Oty	Loc Code	
MAT019	397.96		
117188	3 :		
117766	5		
120604	5 i		
122325	3		
123155	3		
124572	38		
M126647	39.75		
M128254	113.96		
M128435	187.25		
MAT020	12		
124029	2 '		
M126098	10		

			:
			age.
			: 18
			· · · · · · · · · · · · · · · · · · ·
			i , , , , , , , , , , , , , , , , , , ,
		•	
を (本) (本)			ŧ
¥ *			
			1
			•
Miles			· ! !







